

Microcode

GilDev Breadboard Computer

Instruction	Opcode	Step	Flags (NCZ)	HALT	FLGU	MARI	IRGI	RGAI	RGAO	RGBI	RGOI	RGIO	RAMI	RAMO	ALUO	SUBT	PGCI	PGCO	PGCC		
Fetch	XXXX	000	xxx	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1	0		
		001		0	0	0	1	0	0	0	0	0	0	0	1	0	0	0	0	1	
NOP	0000	010	xxx	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
LDA	0001	010	xxx	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0	
		011		0	0	1	0	0	0	0	0	0	0	0	1	0	0	0	0	1	
		100		0	0	0	0	1	0	0	0	0	0	0	1	0	0	0	0	0	
LDI	0010	010	xxx	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0	
		011		0	0	0	0	1	0	0	0	0	0	0	1	0	0	0	0	1	
STA	0011	010	xxx	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0	
		011		0	0	1	0	0	0	0	0	0	0	0	1	0	0	0	0	1	
		100		0	0	0	0	0	1	0	0	0	0	1	0	0	0	0	0	0	
ADD	0100	010	xxx	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0	
		011		0	0	1	0	0	0	0	0	0	0	0	1	0	0	0	0	1	
		100		0	0	0	0	0	0	1	0	0	0	0	1	0	0	0	0	0	
		101		0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
		110		0	0	0	0	1	0	0	0	0	0	0	0	1	0	0	0	0	
ADI	0101	010	xxx	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0	
		011		0	0	0	0	0	0	1	0	0	0	0	1	0	0	0	0	1	
		100		0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
		101		0	0	0	0	1	0	0	0	0	0	0	0	1	0	0	0	0	
SUB	0110	010	xxx	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0	
		011		0	0	1	0	0	0	0	0	0	0	0	1	0	0	0	0	1	
		100		0	0	0	0	0	0	1	0	0	0	0	1	0	0	0	0	0	
		101		0	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	
		110		0	0	0	0	1	0	0	0	0	0	0	0	1	1	0	0	0	
SUI	0111	010	xxx	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0	
		011		0	0	0	0	0	0	1	0	0	0	0	1	0	0	0	0	1	
		100		0	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	
		101		0	0	0	0	1	0	0	0	0	0	0	0	1	1	0	0	0	
JMP	1000	010	xxx	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0	
				0	0	0	0	0	0	0	0	0	0	0	1	0	0	1	0	0	
JPN	1001	010	0xx	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
		010	1xx	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0
		011	1xx	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1	0	0	
JPP	1010	010	xxx	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
		010	0x0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0
		011	0x0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1	0	0	
JPC	1011	010	x0x	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
		010	x1x	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0
		011	x1x	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1	0	0	
JPZ	1100	010	xx0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
		010	xx1	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0
		011	xx1	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1	0	0	
OUT	1101	010	xxx	0	0	0	0	0	1	0	1	0	0	0	0	0	0	0	0		
INP	1110	010	xxx	1	0	0	0	1	0	0	0	1	0	0	0	0	0	0	0		
HLT	1111	010	xxx	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		
Instruction	Opcode	Step	Flags (NCZ)	HALT	FLGU	MARI	IRGI	RGAI	RGAO	RGBI	RGOI	RGIO	RAMI	RAMO	ALUO	SUBT	PGCI	PGCO	PGCC		